

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Amsterdam Road - A	Date Inspected:	5/19/2015
Segment From:	Morris Road	Inspected By:	MHEL
Segment To:	Railroad Trestle (City Line)	Segment ID:	820

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	2
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	1
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		15
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Amsterdam Road - B	Date Inspected:	5/19/2015
Segment From:	Redwood Drive	Inspected By:	MHEL
Segment To:	Morris Road	Segment ID:	821

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	1
Bumps Sags	12 <input type="checkbox"/>	4
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		17
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		83

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Amsterdam Road - C Date Inspected: 5/19/2015  
 Segment From: Sleepy Hollow Road Inspected By: \_\_\_\_\_  
 Segment To: Redwood Drive Segment ID: 822

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	1
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	1
Alligator Cracking	15 <input type="checkbox"/>	1
Bumps Sags	12 <input type="checkbox"/>	1
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	4
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		8
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		92

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Ann Date Inspected: 5/18/2015  
 Segment From: Lorup Inspected By: MHEL  
 Segment To: End Segment ID: 856

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	8
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	3
Polished Aggregate	5 <input type="checkbox"/>	5
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		16
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		84

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Ashlawn Place Date Inspected: 5/19/2015  
 Segment From: Highland Avenue Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 621

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Ashwood Circle	Date Inspected:	5/19/2015
Segment From:	George Huser Drive	Inspected By:	MHEL
Segment To:	Dixie Highway	Segment ID:	819

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			7
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			93

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: <u>Augusta - A</u>	Date Inspected: <u>5/18/2015</u>
Segment From: <u>Rosa</u>	Inspected By: <u>MHEL</u>
Segment To: <u>Bend</u>	Segment ID: <u>823</u>

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	7
Alligator Cracking	15 <input type="checkbox"/>	6
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	4
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		17
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		83

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name: <u>Augusta - B</u>	Date Inspected: <u>5/18/2015</u>
Segment From: <u>Bend</u>	Inspected By: <u>MHEL</u>
Segment To: <u>W Crittenden</u>	Segment ID: <u>1484</u>

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	2
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		2
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		98

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Barbara Circle Date Inspected: 5/18/2015  
 Segment From: Augusta Inspected By: MHEL  
 Segment To: W Crittenden Segment ID: 824

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	4
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		4
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		96

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Barrington Road - A	Date Inspected:	5/19/2015
Segment From:	Dixie Highway	Inspected By:	MHEL
Segment To:	Park Road	Segment ID:	818

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			15
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Barrington Road - B	Date Inspected:	5/19/2015
Segment From:	Park Road	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	602

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	2
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			28
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			72

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Basswood Avenue Date Inspected: 5/18/2015  
 Segment From: Henry Clay Avenue Inspected By: MHEL  
 Segment To: cul-de-sac Segment ID: 580

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Beacon Hill Drive - A (Entrance Date Inspected: 5/18/2015

Segment From: Mount Vernon Inspected By: MHEL

Segment To: Beacon Hill Segment ID: 1485

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	7
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		7
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		93

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Beacon Hill Drive - B	Date Inspected:	5/18/2015
Segment From:	Cul-de-Sac	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	634

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	12	<input type="checkbox"/>	8
Corner / Diagonal Cracks	12	<input type="checkbox"/>	8
Faulting / Blow-up	12	<input type="checkbox"/>	4
Scaling / Spauling	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Patching	10	<input type="checkbox"/>	10
Polished Aggregate	5	<input type="checkbox"/>	5
Joint Condition	10	<input type="checkbox"/>	10
<b>Sum of Defects =</b>			48
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			52

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Beaumont Court - A	Date Inspected:	5/18/2015
Segment From:	Highland Pike	Inspected By:	MHEL
Segment To:	Mount Vernon Drive	Segment ID:	816

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	4
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Beaumont Court - B Date Inspected: 5/18/2015  
 Segment From: Mt. Vernon Drive Inspected By: MHEL  
 Segment To: Montpelier Court Segment ID: 632

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes: Scheduled for Reconstruction 2015

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Birchwood Drive Date Inspected: 5/19/2015  
 Segment From: Park Road Inspected By: MHEL  
 Segment To: Amsterdam Road Segment ID: 807

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	1
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	1
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	4
Polished Aggregate	7 <input type="checkbox"/>	1
<b>Sum of Defects =</b>		19
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		81

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Bluegrass Avenue Date Inspected: 5/18/2015  
 Segment From: Henry Clay Street Inspected By: MHEL  
 Segment To: end Segment ID: 628

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	4
<b>Sum of Defects =</b>		8
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		92

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Bunker	Date Inspected:	5/19/2015
Segment From:	end	Inspected By:	MHEL
Segment To:	Fort Henry	Segment ID:	825

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Cherokee	Date Inspected:	5/19/2015
Segment From:	End	Inspected By:	MHEL
Segment To:	Morris	Segment ID:	826

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			14
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			86

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Chestnut Court Date Inspected: 5/19/2015  
 Segment From: Redwood Drive Inspected By: MHEL  
 Segment To: cul-de-sac Segment ID: 604

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	3
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Christine Court	Date Inspected:	5/18/2015
Segment From:	Henry Clay Avenue	Inspected By:	MHEL
Segment To:	End	Segment ID:	581

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	15
Alligator Cracking	15	<input type="checkbox"/>	15
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	4
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			50
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			50

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Civil War Museum Entrance Dri Date Inspected: 5/19/2015  
 Segment From: End Inspected By: MHELLMANN  
 Segment To: Highland Ave Segment ID: 1503

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	9
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	3
Bumps Sags	12 <input type="checkbox"/>	8
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		32
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		68

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Community of Faith Church Ent Date Inspected: 5/19/2015  
 Segment From: Highland Ave Inspected By: MHELLMANN  
 Segment To: Parking Lot Segment ID: 1501

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	3
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	7
Alligator Cracking	15 <input type="checkbox"/>	4
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		14
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		86

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Community of Faith Church Par Date Inspected: 5/19/2015  
 Segment From: End Inspected By: MHELLMANN  
 Segment To: Entrance Drive Segment ID: 1502

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	3
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	9
Alligator Cracking	15 <input type="checkbox"/>	9
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	1
<b>Sum of Defects =</b>		30
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		70

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Cumberland Avenue Date Inspected: 5/18/2015  
 Segment From: Kyles Lane Inspected By: MHEL  
 Segment To: Basswood Avenue Segment ID: 583

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Don Martin Date Inspected: 5/19/2015  
 Segment From: Lookout Heights Inspected By: MHEL  
 Segment To: End Segment ID: 855

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		2
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

**Notes:** -Segmental Block Wall at end appears to be failing. Portion of the sidewalk and the roadway pavement in the T-turnaround are sinking as a result.

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Dorisway Drive	Date Inspected:	5/18/2015
Segment From:	Williams Creek Way	Inspected By:	MHEL
Segment To:	End	Segment ID:	1486

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	0
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			1
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			99

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Dudley	Date Inspected:	5/18/2015
Segment From:	Madison Pike	Inspected By:	MHEL
Segment To:	End	Segment ID:	827

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	1
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	4
<b>Sum of Defects =</b>			9
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			91

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes: -Bridge

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: E Crittenden Avenue Date Inspected: 5/18/2015  
 Segment From: Kyles Lane Inspected By: MHEL  
 Segment To: Basswood Avenue Segment ID: 582

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	E Henry Clay - A	Date Inspected:	5/18/2015
Segment From:	Kyles	Inspected By:	MHEL
Segment To:	Henry Clay Ct	Segment ID:	829

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	2
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			22
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			78

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	E Henry Clay - B	Date Inspected:	5/18/2015
Segment From:	Henry Clay Ct	Inspected By:	MHEL
Segment To:	Upland	Segment ID:	828

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	1
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			2
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			98

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	E Henry Clay - C	Date Inspected:	5/18/2015
Segment From:	Upland	Inspected By:	MHEL
Segment To:	Highland	Segment ID:	1487

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	1
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			2
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			98

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Eaton Drive Date Inspected: 5/20/2015  
 Segment From: Madison Pike (KY17) Inspected By: \_\_\_\_\_  
 Segment To: Bridge Segment ID: 815

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	9
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	2
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	4
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		15
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

**Notes:** -Large sections where the asphalt surface has sheared off due to large truck traffic

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name: Edna Lane Date Inspected: 5/18/2015  
 Segment From: Augusta Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 587

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	9
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	15
Alligator Cracking	15 <input type="checkbox"/>	15
Bumps Sags	12 <input type="checkbox"/>	8
Deficient Drainage	12 <input type="checkbox"/>	4
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	12
Polished Aggregate	7 <input type="checkbox"/>	7
<b>Sum of Defects =</b>		70
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		30

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Elder Court Date Inspected: 5/19/2015  
 Segment From: Redwood Drive Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 605

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	4
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	3
Polished Aggregate	5 <input type="checkbox"/>	5
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		14
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		86

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes: -Needs a Couple concrete slabs replaced

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Farrell	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	Private Drive	Segment ID:	830

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	16
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			25
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			75

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Fayette	Date Inspected:	5/18/2015
Segment From:	E Henry Clay	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	831

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	4
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Fort Henry Drive - A	Date Inspected:	5/19/2015
Segment From:	Amsterdam Road	Inspected By:	MHEL
Segment To:	422 Fort Henry	Segment ID:	608

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Fort Henry Drive - B	Date Inspected:	5/19/2015
Segment From:	422 Fort Henry	Inspected By:	MHEL
Segment To:	434 Fort Henry	Segment ID:	1488

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Fort Henry Drive - C	Date Inspected:	5/19/2015
Segment From:	434 Fort Henry	Inspected By:	MHEL
Segment To:	Lookout Ct	Segment ID:	1489

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			9
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			91

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Fort Henry Drive - D	Date Inspected:	5/19/2015
Segment From:	Lookout Court	Inspected By:	MHEL
Segment To:	Pickett Drive	Segment ID:	649

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Fort Henry Drive - E	Date Inspected:	5/19/2015
Segment From:	Pickett Drive	Inspected By:	MHEL
Segment To:	General Drive	Segment ID:	610

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			8
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			92

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

**Notes:** Curbs are crumbling throughout

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	General Drive - A	Date Inspected:	5/19/2015
Segment From:	Amsterdam Road	Inspected By:	MHEL
Segment To:	Pickett Drive	Segment ID:	651

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	2
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	General Drive - B	Date Inspected:	5/19/2015
Segment From:	Pickett Drive	Inspected By:	MHEL
Segment To:	High Point Drive	Segment ID:	650

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			9
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			91

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	General Drive - C	Date Inspected:	5/19/2015
Segment From:	High Point Drive	Inspected By:	MHEL
Segment To:	Fort Henry Drive	Segment ID:	611

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			15
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	General Drive - D	Date Inspected:	5/19/2015
Segment From:	Fort Henry Drive	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	1490

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	9
Alligator Cracking	15	<input type="checkbox"/>	2
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			20
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			80

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	George Huser Drive	Date Inspected:	5/19/2015
Segment From:	Dixie Highway	Inspected By:	MHEL
Segment To:	Park Road	Segment ID:	817

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			5
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			95

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Glasgow Court	Date Inspected:	5/19/2015
Segment From:	Glengarry Way	Inspected By:	MHELLMANN
Segment To:	Cul-de-Sac	Segment ID:	643

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	1
Alligator Cracking	15 <input type="checkbox"/>	3
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	4
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		8
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		92

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Glazier Court Date Inspected: 5/19/2015  
 Segment From: Barrington Road Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 607

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	1
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	2
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	5
Joint Condition	10 <input type="checkbox"/>	6
<b>Sum of Defects =</b>		16
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		84

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Glazier Road	Date Inspected:	5/19/2015
Segment From:	Morris Place	Inspected By:	MHEL
Segment To:	Barrington	Segment ID:	603

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	12	<input type="checkbox"/>	0
Corner / Diagonal Cracks	12	<input type="checkbox"/>	0
Faulting / Blow-up	12	<input type="checkbox"/>	0
Scaling / Spauling	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Patching	10	<input type="checkbox"/>	0
Polished Aggregate	5	<input type="checkbox"/>	0
Joint Condition	10	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			0
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Glengarry Way	Date Inspected:	5/19/2015
Segment From:	Fort Henry Drive	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	802

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			12
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			88

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

**City of Fort Wright**  
**Pavement Condition Rating**



**100\_B - Concrete**

Street Name: Goebel Court Date Inspected: 5/19/2015  
 Segment From: Morris Road Inspected By: MHEL  
 Segment To: cul-de-sac Segment ID: 606

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	3
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Hazlewood Drive	Date Inspected:	5/19/2015
Segment From:	Park Road	Inspected By:	MHEL
Segment To:	Redwood Drive	Segment ID:	806

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			18
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			82

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Helen Ruth Date Inspected: 5/18/2015  
 Segment From: Old KY17 Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 653

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	9
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	8
Corner / Diagonal Cracks	12 <input type="checkbox"/>	8
Faulting / Blow-up	12 <input type="checkbox"/>	8
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	6
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	10
<b>Sum of Defects =</b>		49
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		51

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Hermitage Date Inspected: 5/18/2015  
 Segment From: Monticello Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 832

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		1
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		99

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	High Point Drive	Date Inspected:	5/19/2015
Segment From:	General Drive	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	598

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	9
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			31
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			69

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Highland Pike	Date Inspected:	5/19/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	City Line/Covington	Segment ID:	1491

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			6
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			94

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Highland Place	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	End	Segment ID:	833

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			12
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			88

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Highview Drive	Date Inspected:	5/18/2015
Segment From:	Rivard	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	585

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	1
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			6
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			94

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Howard Road	Date Inspected:	5/19/2015
Segment From:	Barrington Road	Inspected By:	MHEL
Segment To:	Morris Road	Segment ID:	601

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			19
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			81

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Kennedy - A	Date Inspected:	5/18/2015
Segment From:	Kyles	Inspected By:	MHEL
Segment To:	Rosa	Segment ID:	834

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	8
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			24
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			76

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Kennedy - B Date Inspected: 5/18/2015  
 Segment From: Rosa Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 835

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		2
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Kentucky	Date Inspected:	5/18/2015
Segment From:	Highland	Inspected By:	MHEL
Segment To:	Lorup	Segment ID:	836

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	4
<b>Sum of Defects =</b>			13
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			87

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Knob Hill Date Inspected: 5/18/2015  
 Segment From: Mt. Vernon Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 837

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	2
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		2
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Kyles Place	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	End	Segment ID:	1492

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	9
Alligator Cracking	15	<input type="checkbox"/>	6
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	1
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			30
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			70

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Lake Street - A	Date Inspected:	5/18/2015
Segment From:	Kennedy Rd	Inspected By:	MHEL
Segment To:	North Cul-de-Sac	Segment ID:	838

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	12	<input type="checkbox"/>	2
Corner / Diagonal Cracks	12	<input type="checkbox"/>	0
Faulting / Blow-up	12	<input type="checkbox"/>	0
Scaling / Spauling	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Patching	10	<input type="checkbox"/>	0
Polished Aggregate	5	<input type="checkbox"/>	0
Joint Condition	10	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			2
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Lake Street - B	Date Inspected:	5/18/2015
Segment From:	Kennedy Road	Inspected By:	MHEL
Segment To:	South Cul-de-Sac	Segment ID:	1493

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	12	<input type="checkbox"/>	2
Corner / Diagonal Cracks	12	<input type="checkbox"/>	0
Faulting / Blow-up	12	<input type="checkbox"/>	0
Scaling / Spauling	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Patching	10	<input type="checkbox"/>	0
Polished Aggregate	5	<input type="checkbox"/>	0
Joint Condition	10	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			2
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Lookout Court	Date Inspected:	5/19/2015
Segment From:	Fort Henry	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	839

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			9
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			91

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Lookout Heights Lane      Date Inspected: 5/19/2015  
 Segment From: Sleepy Hollow Road      Inspected By: MHEL  
 Segment To: End      Segment ID: 814

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	4
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	3
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		9
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		91

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Lorup Avenue	Date Inspected:	5/18/2015
Segment From:	Highland Pike	Inspected By:	MHEL
Segment To:	Kyles Lane	Segment ID:	809

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	6
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	8
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			22
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			78

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Marcella	Date Inspected:	5/18/2015
Segment From:	St. Anthony	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	840

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			8
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			92

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Monticello Drive - A	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	Ashlawn Place	Segment ID:	1495

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	4
<b>Sum of Defects =</b>			12
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			88

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Monticello Drive - B Date Inspected: 5/18/2015  
 Segment From: Ashlawn Place Inspected By: MHEL  
 Segment To: Normandy Segment ID: 623

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Monticello Drive - C	Date Inspected:	5/18/2015
Segment From:	Normandy	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	1494

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		4
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		96

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Montpelier Date Inspected: 5/18/2015  
 Segment From: Mt. Vernon Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 842

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		4
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		96

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Morris Place	Date Inspected:	5/19/2015
Segment From:	Park Road	Inspected By:	MHEL
Segment To:	Glazier Court	Segment ID:	619

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	12	<input type="checkbox"/>	0
Corner / Diagonal Cracks	12	<input type="checkbox"/>	0
Faulting / Blow-up	12	<input type="checkbox"/>	0
Scaling / Spauling	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Patching	10	<input type="checkbox"/>	0
Polished Aggregate	5	<input type="checkbox"/>	0
Joint Condition	10	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			0
<b>Sum of Structural Deducts (☑)=</b>			0
<b>PCR =</b>			100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes: Rebuilt 2013

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Morris Road - A	Date Inspected:	5/19/2015
Segment From:	Amsterdam Road	Inspected By:	MHEL
Segment To:	Howard Road	Segment ID:	600

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	4
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			24
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			76

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Morris Road - B	Date Inspected:	5/19/2015
Segment From:	Amsterdam Rd	Inspected By:	MHEL
Segment To:	Cherokee Dr	Segment ID:	1496

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			9
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			91

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Morris Road - C Date Inspected: 5/19/2015  
 Segment From: Cherokee Dr Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 631

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	2
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes: Needs a couple of spot repairs

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - A	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	Beaumont Court	Segment ID:	812

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	7
Alligator Cracking	15 <input type="checkbox"/>	1
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	1
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		9
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		91

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Mount Vernon Drive - B Date Inspected: 5/18/2015  
 Segment From: Beaumont Court Inspected By: MHEL  
 Segment To: Beacon Hill Drive Segment ID: 813

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	1
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	9
Alligator Cracking	15 <input type="checkbox"/>	5
Bumps Sags	12 <input type="checkbox"/>	1
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	1
Patching	12 <input type="checkbox"/>	4
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		21
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		79

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - C	Date Inspected:	5/18/2015
Segment From:	Beacon Hill Drive	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	635

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			10
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			90

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Normandy Court Date Inspected: 5/18/2015  
 Segment From: Monticello Drive Inspected By: MHEL  
 Segment To: Cul-de-Sac Segment ID: 622

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		0
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		100

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Oak Hill Court	Date Inspected:	5/18/2015
Segment From:	Mt. Vernon Drive	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	626

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	15
Alligator Cracking	15	<input type="checkbox"/>	9
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	12
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			58
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			42

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Old Horsebranch Road      Date Inspected: 5/18/2015  
 Segment From: Orphanage Road      Inspected By: MHEL  
 Segment To: End      Segment ID: 811

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	3
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	9
Alligator Cracking	15 <input type="checkbox"/>	9
Bumps Sags	12 <input type="checkbox"/>	4
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	8
Patching	12 <input type="checkbox"/>	1
Polished Aggregate	7 <input type="checkbox"/>	1
<b>Sum of Defects =</b>		35
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		65

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Old KY 17	Date Inspected:	5/18/2015
Segment From:	Madison Pike	Inspected By:	MHEL
Segment To:	city line	Segment ID:	652

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	9
Alligator Cracking	15	<input type="checkbox"/>	9
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			35
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			65

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Old State Road	Date Inspected:	5/18/2015
Segment From:	Sleepy Hollow Road	Inspected By:	MHEL
Segment To:	City Line	Segment ID:	629

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			17
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			83

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Olivia	Date Inspected:	5/18/2015
Segment From:	Highland	Inspected By:	MHEL
Segment To:	Lorup	Segment ID:	843

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	12
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			25
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			75

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Park Road	Date Inspected:	5/19/2015
Segment From:	Morris	Inspected By:	MHEL
Segment To:	Barrington	Segment ID:	844

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	2
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			16
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			84

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Parkside Place Date Inspected: 5/27/2015  
 Segment From: Cul-de-Sac Inspected By: \_\_\_\_\_  
 Segment To: Cul-de-Sac Segment ID: 637

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	4
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		4
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		96

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Pickett Ct	Date Inspected:	5/19/2015
Segment From:	Pickett Dr	Inspected By:	MHEL
Segment To:	Cul-se-Sac	Segment ID:	1498

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			15
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Pickett Drive - A	Date Inspected:	5/19/2015
Segment From:	General Drive	Inspected By:	MHEL
Segment To:	Pickett Court	Segment ID:	599

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			6
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			94

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Pickett Drive - B	Date Inspected:	5/19/2015
Segment From:	Pickett Ct	Inspected By:	MHEL
Segment To:	Fort Henry	Segment ID:	1497

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			15
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			85

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Pieck Drive - A	Date Inspected:	5/18/2015
Segment From:	City Line	Inspected By:	MHEL
Segment To:	#1953	Segment ID:	641

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	3
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	15
Alligator Cracking	15 <input type="checkbox"/>	9
Bumps Sags	12 <input type="checkbox"/>	8
Deficient Drainage	12 <input type="checkbox"/>	4
Edge Cracking / Raveling	12 <input type="checkbox"/>	12
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	7
<b>Sum of Defects =</b>		58
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		42

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Pieck Drive - B	Date Inspected:	5/18/2015
Segment From:	#1953	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	642

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			6
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			94

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Pine Hurst Date Inspected: 5/27/2015  
 Segment From: Cul-de-Sac Inspected By: MHEL  
 Segment To: City Line Segment ID: 845

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		3
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		97

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Redwood Drive	Date Inspected:	5/19/2015
Segment From:	Park Road	Inspected By:	MHEL
Segment To:	Amsterdam Road	Segment ID:	805

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			14
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			86

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Reeves Drive	Date Inspected:	5/18/2015
Segment From:	Highland Avenue	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	625

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	3
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	13
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	4
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	12
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			50
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			50

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Ridgemont	Date Inspected:	5/18/2015
Segment From:	Henry Clay	Inspected By:	MHEL
Segment To:	End	Segment ID:	846

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	10
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	5
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			26
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			74

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Rivard Drive - A	Date Inspected:	5/18/2015
Segment From:	Kennedy	Inspected By:	MHEL
Segment To:	Highview	Segment ID:	586

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	10
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			35
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			65

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Rivard Drive - B	Date Inspected:	5/18/2015
Segment From:	High View	Inspected By:	MHEL
Segment To:	Dixie	Segment ID:	847

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	4
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			25
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			75

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Rosa Ave	Date Inspected:	5/18/2015
Segment From:	W. Crittenden	Inspected By:	MHEL
Segment To:	Kennedy	Segment ID:	848

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			12
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			88

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Rosa Ct Date Inspected: 5/18/2015  
 Segment From: Kennedy Inspected By: MHEL  
 Segment To: End Segment ID: 1499

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	8
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		8
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		92

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Sentinel Point	Date Inspected:	5/19/2015
Segment From:	General	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	849

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			20
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			80

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: South Hills Civic Club Parking L Date Inspected: 5/18/2015  
 Segment From: All Inspected By: MHEL  
 Segment To: \_\_\_\_\_ Segment ID: 1500

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	7
<b>Sum of Defects =</b>		11
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		89

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

**City of Fort Wright**  
**Pavement Condition Rating**



**100\_B - Concrete**

Street Name: St. Agnes Circle Date Inspected: 5/19/2015  
 Segment From: Park Road Inspected By: MHEL  
 Segment To: Vidot Court Segment ID: 588

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	1
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		4
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		96

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	St. Anthony	Date Inspected:	5/18/2015
Segment From:	Kyles Lane	Inspected By:	MHEL
Segment To:	End	Segment ID:	841

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	4
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	1
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		95

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Stonewell Trail Date Inspected: 5/18/2015  
 Segment From: Longmeadow Inspected By: MHEL  
 Segment To: Parkside Place Segment ID: 636

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	4
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	4
<b>Sum of Defects =</b>		8
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		92

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Stoney Point	Date Inspected:	5/19/2015
Segment From:	General	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	850

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	2
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	8
Patching	12	<input type="checkbox"/>	8
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			30
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			70

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Tartan Drive	Date Inspected:	5/19/2015
Segment From:	Glengarry Way	Inspected By:	MHEL
Segment To:	Cul-de-Sac	Segment ID:	803

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	4
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			11
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			89

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name:	Tyler Court	Date Inspected:	5/19/2015
Segment From:	Fort Henry Drive	Inspected By:	MHELLMANN
Segment To:	Cul-de-Sac	Segment ID:	630

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	0
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	0
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		2
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		98

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Upland	Date Inspected:	5/18/2015
Segment From:	Henry Clay	Inspected By:	MHELLMANN
Segment To:	End	Segment ID:	851

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	2
Alligator Cracking	15	<input type="checkbox"/>	1
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	4
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	5
Polished Aggregate	7	<input type="checkbox"/>	4
<b>Sum of Defects =</b>			20
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			80

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Valley Drive Date Inspected: 5/18/2015  
 Segment From: Kyles Lane Inspected By: MHELLMANN  
 Segment To: Cul-de-Sac Segment ID: 645

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	3
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (☑)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	Valley Plaza Parkway	Date Inspected:	5/18/2015
Segment From:	Highland Pike	Inspected By:	MHELLMANN
Segment To:	Orphanage Road	Segment ID:	810

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	2
Alligator Cracking	15	<input type="checkbox"/>	0
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	4
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	0
<b>Sum of Defects =</b>			11
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			89

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Vidot Court Date Inspected: 5/19/2015  
 Segment From: Amsterdam Road Inspected By: MHELLMANN  
 Segment To: Cul-de-Sac Segment ID: 596

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Concrete

Street Name: Viewpoint Drive Date Inspected: 5/19/2015  
 Segment From: Valley Plaza Parkway Inspected By: MHELLMAN  
 Segment To: end of pavement Segment ID: 594

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	12 <input type="checkbox"/>	2
Corner / Diagonal Cracks	12 <input type="checkbox"/>	0
Faulting / Blow-up	12 <input type="checkbox"/>	0
Scaling / Spauling	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Patching	10 <input type="checkbox"/>	1
Polished Aggregate	5 <input type="checkbox"/>	0
Joint Condition	10 <input type="checkbox"/>	2
<b>Sum of Defects =</b>		5
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		95

**Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)**

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	W Crittenden	Date Inspected:	5/18/2015
Segment From:	Barbara	Inspected By:	MHELLMAN
Segment To:	Kyles	Segment ID:	853

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	4
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	2
Patching	12	<input type="checkbox"/>	1
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			24
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			76

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name:	W Henry Clay	Date Inspected:	5/18/2015
Segment From:	Rosa	Inspected By:	MHELLMANN
Segment To:	Kyles	Segment ID:	852

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	0
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	16
Alligator Cracking	15	<input type="checkbox"/>	5
Bumps Sags	12	<input type="checkbox"/>	0
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	1
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	7
<b>Sum of Defects =</b>			29
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			71

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name:	Werner Drive	Date Inspected:	5/18/2015
Segment From:	Highland Pike	Inspected By:	MHELLMANN
Segment To:	Lorup Avenue	Segment ID:	808

DISTRESS TYPE	DISTRESS WEIGHT		RATING
Pot Holes	15	<input type="checkbox"/>	1
Transverse Longitudinal Cracking	15	<input type="checkbox"/>	7
Alligator Cracking	15	<input type="checkbox"/>	3
Bumps Sags	12	<input type="checkbox"/>	1
Deficient Drainage	12	<input type="checkbox"/>	0
Edge Cracking / Raveling	12	<input type="checkbox"/>	0
Patching	12	<input type="checkbox"/>	0
Polished Aggregate	7	<input type="checkbox"/>	1
<b>Sum of Defects =</b>			13
<b>Sum of Structural Deducts (✓)=</b>			0
<b>PCR =</b>			87

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright Pavement Condition Rating



## 100\_B - Asphalt

Street Name: Williams Creek Date Inspected: 5/18/2015  
 Segment From: end Inspected By: MHELLMANN  
 Segment To: Old Ky 17 Segment ID: 854

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	0
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	1
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		1
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		99

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Wolfzorn Court Date Inspected: 5/18/2015  
 Segment From: Mt. Vernon Inspected By: MHELLMANN  
 Segment To: Cul-de-Sac Segment ID: 624

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	9
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	15
Alligator Cracking	15 <input type="checkbox"/>	15
Bumps Sags	12 <input type="checkbox"/>	4
Deficient Drainage	12 <input type="checkbox"/>	1
Edge Cracking / Raveling	12 <input type="checkbox"/>	0
Patching	12 <input type="checkbox"/>	4
Polished Aggregate	7 <input type="checkbox"/>	7
<b>Sum of Defects =</b>		55
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		45

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes:

# City of Fort Wright

## Pavement Condition Rating



### 100\_B - Asphalt

Street Name: Wrights Summit Parkway      Date Inspected: 6/5/2015  
 Segment From: Dixie Highway      Inspected By: MHELLMANN  
 Segment To: Kyles Lane      Segment ID: 648

DISTRESS TYPE	DISTRESS WEIGHT	RATING
Pot Holes	15 <input type="checkbox"/>	1
Transverse Longitudinal Cracking	15 <input type="checkbox"/>	1
Alligator Cracking	15 <input type="checkbox"/>	0
Bumps Sags	12 <input type="checkbox"/>	0
Deficient Drainage	12 <input type="checkbox"/>	0
Edge Cracking / Raveling	12 <input type="checkbox"/>	4
Patching	12 <input type="checkbox"/>	0
Polished Aggregate	7 <input type="checkbox"/>	0
<b>Sum of Defects =</b>		6
<b>Sum of Structural Deducts (✓)=</b>		0
<b>PCR =</b>		94

***Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)***

Notes: